



Bode Electric Door Update Kit for BBCV

UPDATE

Models Affected: BBCV Vision Buses with Feature 30977-11 Door, Entrance, Bode, Outward Opening Door with Electric Door Control.

ISSUE

Bode has released an updated electric door drive plate assembly for the Bode electric outward opening entrance door on the BBCV Vision products. This updated assembly is now available as a kit through Blue Bird Service Parts.

PROCEDURE

WARNING: Always follow all Federal, State, Local and Shop safety standards and use proper safety equipment when performing these procedures.

1. Park the bus on a level surface, apply parking brakes, turn off engine and remove keys. Chock wheels.
2. Disconnect batteries – Note; When disconnecting the batteries, remove the Negative cable first.
3. Follow step by step instructions provided in Kit 10020568 to update the Bode door drive plate and header cover.
4. Reconnect batteries – Note, when connecting the batteries, connect the Positive cable first.

PARTS

PART NUMBER	QTY	DESCRIPTION
10020568	1	Kit, Drive Plate Emer. Release Rework, Bode

Contact Blue Bird Service Parts for kit availability and price.

S1005

S E R V I C E U P D A T E