DATE: OCTOBER 26, 2006

SUBJECT: SERVICE UPDATE S0612 SPECTAL WINDOW

LATCH KIT

MODELS AFFECTED: ALL SCHOOL BUSES WITH SPECTAL WINDOWS

You will find enclosed a copy of Service Update S0612 regarding broken springs or spring retainer tabs on Spectal passenger window latches.

Replacement latch retainer repair kits are now available in limited quantities. However, these kits are not in Part Sales inventory. Request for repair kits must be sent to Bill Coleman at Blue Bird in Fort Valley. You may fax your request to 478-822-2467 or email your request to wpcolema@blue-bird.com.

Questions regarding Service Update S0612 should be directed to your Blue Bird Customer Service Representative.



UPDATE

Spectal Window Latch Repair Kit

MODELS AFFECTED: All School Buses with Spectal Windows

ISSU


Window latch spring retainer tab breaks.


APPLICATIONS

Install Spectal latch retainer kit on each broken window latch.

INSTRUCTIONS

- 1. Insert the spring in to the plastic base.
- 2. Snap the part into place as shown on the following diagram.





2

9

0

S