

March 03, 2011

SERVICE MEMORANDUM NO. SM1103

MEMO TO: All Blue Bird Dealers

SUBJECT: Ricon and Braun Wheelchair Lift Mounting Bolts

MODEL YEAR: 2011

MODELS AFFECTED: A3FE, A3RE, BBCV, D3FE & D3RE

Blue Bird installed lifts by Ricon or Braun only require (8) mounting fasteners thru the base mounting plate to the floor. The lift base mounting plates contain (10) mounting holes, the (2) holes located in the center of the base mounting plate are not used and do not require fasteners.

Sincerely,
Bill Coleman

Bill Coleman

Blue Bird Engineering Services

bill.coleman@blue-bird.com

478-822-2242